


Wood Screw Diameters



| Size Number | Major Thread Diameter* | |
|-------------|------------------------|--------------------------------|
| | Decimal | Nearest Fractional Measurement |
| 0 | .060 | 1/16 |
| 1 | .073 | 5/64 |
| 2 | .086 | 3/32 |
| 3 | .099 | 7/64 |
| 4 | .112 | 7/64 |
| 5 | .125 | 1/8 |
| 6 | .138 | 9/64 |
| 7 | .151 | 5/32 |
| 8 | .164 | 5/32 |
| 9 | .177 | 11/64 |
| 10 | .190 | 3/16 |
| 11 | .203 | 13/64 |
| 12 | .216 | 7/32 |
| 14 | .242 | 1/4 |
| 16 | .268 | 17/64 |
| 18 | .294 | 19/64 |
| 20 | .320 | 5/16 |

* Major thread diameter is measured on the outside of the threads.

